

Lp.	Podst	Opis i wyliczenia	j.m.	Poszcz	Razem
<b>1 I. Wymiana stolarki otworowej - profili PCV, wg z Specyfikacja Techniczna CPV 45451125-5</b>					
1	<b>KNR 0-19</b>	Wymiana okien skrzynkowych na okna rozwierane i uchylno-rozwierane dwu-	m <sup>2</sup>		
d.1	<b>0930-08</b>	dzielne z PCV o pow. do 1.5 m2			
	<b>ST 2.1.3.2a</b>				
	<b>lp</b>	(1.15*1.20)*1	m <sup>2</sup>	1.380	
	<b>gab. kom.</b>	(1.15*1.20)*1	m <sup>2</sup>	1.380	
	<b>lp/toaleta</b>	(1.00*0.50)*2	m <sup>2</sup>	1.000	
	<b>gab.gosp</b>	(1.15*1.20)*1	m <sup>2</sup>	1.380	
	<b>kl.sch</b>	(1.10*0.90)*1	m <sup>2</sup>	0.990	
	<b>toaleta m</b>	(0.64*1.46)*1	m <sup>2</sup>	0.934	
	<b>toaleta d</b>	(0.84*1.46)*1	m <sup>2</sup>	1.226	
	<b>toaleta d</b>	(0.83*1.46)*1	m <sup>2</sup>	1.212	
	<b>korytaz</b>	(1.20*1.12)*1	m <sup>2</sup>	1.344	
				<b>RAZEM</b>	<b>10.846</b>
2	<b>KNR 0-19</b>	Wymiana okien skrzynkowych na okna rozwierane i uchylno-rozwierane dwu-	m <sup>2</sup>		
d.1	<b>0930-10</b>	dzielne z PCV o pow. do 2.5 m2			
	<b>ST 2.1.3.2a</b>				
	<b>gab. kom.</b>	(1.73*1.56)*1	m <sup>2</sup>	2.699	
	<b>kl. sch</b>	(1.20*2.00)*1	m <sup>2</sup>	2.400	
	<b>sal.komput</b>	(1.90*1.94)*1	m <sup>2</sup>	3.686	
	<b>holl/wejscie</b>	(1.93*1.96)*1	m <sup>2</sup>	3.783	
				<b>RAZEM</b>	<b>12.568</b>
3	<b>KNR 0-19</b>	Wymiana okien skrzynkowych na okna uchylne jednodzielne z PCV o pow. do	m <sup>2</sup>		
d.1	<b>0930-03</b>	1.0 m2			
	<b>ST 2.1.3.2a</b>				
	<b>holl mbp</b>	(0.82*1.15)*2	m <sup>2</sup>	1.886	
				<b>RAZEM</b>	<b>1.886</b>
4	<b>KNR 0-19</b>	Wymiana okien skrzynkowych na okna uchylne jednodzielne z PCV o pow. do	m <sup>2</sup>		
d.1	<b>0930-01</b>	0.4 m2			
	<b>ST 2.1.3.2a</b>				
	<b>mbp</b>	(0.47*0.45)*1	m <sup>2</sup>	0.212	
	<b>korytaz</b>	(0.70*0.50)*1	m <sup>2</sup>	0.350	
				<b>RAZEM</b>	<b>0.562</b>
5	<b>KNR 0-19</b>	Wymiana okien skrzynkowych na okna uchylne jednodzielne z PCV o pow. do	m <sup>2</sup>		
d.1	<b>0930-03</b>	1.0 m2			
	<b>ST 2.1.3.2a</b>				
	<b>korytaz</b>	(0.70*1.12)*1	m <sup>2</sup>	0.784	
				<b>RAZEM</b>	<b>0.784</b>
6	<b>KNR 0-19</b>	Wymiana drzwi balkonowych skrzynkowych na drzwi balkonowe z PCV dwu-	m <sup>2</sup>		
d.1	<b>0930-12</b>	dzielne z naswietlem. 1,59*(2.14+0,56) szt.1			
	<b>ST 2.1.3.2b</b>				
	<b>sal.komput</b>	(1.59*2.70)*1	m <sup>2</sup>	4.293	
				<b>RAZEM</b>	<b>4.293</b>
7	<b>KNR 4-01</b>	Wykucie z muru podokienników wew.	m		
d.1	<b>0354-11</b>				
	<b>ST 2.1.3.2c</b>				
		24.13	m	24.130	
				<b>RAZEM</b>	<b>24.130</b>
8	<b>KNR-W 2-</b>	Spadki pod parapety z zaprawy cem. M12	m <sup>2</sup>		
d.1	<b>02 0921-04</b>				
	<b>ST 2.1.3.2d</b>				
		24.13*0.20	m <sup>2</sup>	4.826	
				<b>RAZEM</b>	<b>4.826</b>
9	<b>NNRNKB</b>	Montaż podokienników - parapetów wew P-PCV 300	m		
d.1	<b>202 0539-02</b>				
	<b>ST 2.1.3.2e</b>				
		1.35*2+1.93+1.20*2+1.35+1.30+1.40*2+2.10+1.02*2+0.67+0.90*2+2.13+0.84+1.04+1.03	m	24.130	
				<b>RAZEM</b>	<b>24.130</b>